



4T40-E, 4T45-E

NO TCC APPLY, HIGH TCC SLIPPAGE,
CODE 741, SOFT OR HARSH TCC APPLY
TCC REGULATED APPLY SLEEVE
33000-02



REQUIRES TOOL 33000-TL

TORQUE CONVERTER CONTROL, CONVERTER OVERHEATS
APPLY AND RELEASE PROBLEMS
TCC CONTROL VALVE SLEEVE
4T40E.VA02




REQUIRES TOOL 4T40E.VA10*

LOW OR HIGH LINE PRESSURE SURGE
PUMP ROTOR FAILURE AND NOISE
OVERSIZED PRESSURE REGULATOR VALVE
4T40E.VA05



REQUIRES TOOL 4T40E.VA06

HIGH OR LOW LINE PRESSURE
HARSH OR SOFT SHIFTS, DELAYED OR NO REVERSE
BOOST VALVE & SLEEVE KIT
4T40E.VA07



WRONG GEAR STARTS, SOLENOID CODES, 1811 CODE
AFL VALVE SLEEVE KIT
4T40E.VA04



REQUIRES TOOL 4T40E.VA11

WORN CHANNEL PLATE SLEEVE
CHANNEL PLATE SLEEVE KIT
4T40E.SL01

